


Calibrated touch screen

If the touch is not accurate, you can calibrate it with infrared configuration software

out. 26, 2025

Resources	2021/8/21 16:35	文件夹
InfraRed_SwConfig	2023/9/15 11:35	配置设置
InfraRedTouch	2021/8/21 16:40	应用程序
multitouch_hw_port.dll	2021/8/21 16:31	应用程序扩展
multitouch_hw_service.dll	2021/8/21 16:31	应用程序扩展
TC9_Win_800000119(1).hwf	2021/7/26 15:35	HWF 文件
WhiteBoard	2021/9/3 11:02	快捷方式

1.open the infrared configuration software.(Double click InfraRedTouch)



2. Click “Equipment Calibration”

3. Place your finger in the center of the cue point until it prompts the next point

Calibration video below